



## **Whitehorse International Airport Notification of VOR Replacement**

NAV CANADA wishes to inform its customers that the Very High Frequency Omni-Directional Range (VOR) at Whitehorse International Airport, Yukon will be shutdown for maintenance during the fall of 2009. The maintenance of a new VOR system at Whitehorse will address life cycle reliability and integrity of service issues.

The current VOR supports airway structures and the missed approach procedure for the LOC (BC)/NDB/DME RWY 13R at Whitehorse International. As a result of the replacement project, the VOR will be unavailable for approximately one week. During this period all other navigation aids at the airport will remain operational to maximize airport accessibility.

The planned outage period for the VOR is from **07 September to 14 September 2009**. Dates are subject to change depending upon weather conditions and contractor availability. Actual dates of scheduled outage will be published via NOTAM. Pilots should carefully monitor the NOTAM before and during the construction period for specific dates of the outage or other related disruptions.

NAV CANADA regrets any inconvenience to its customers; however, the importance of this navigation aid is recognised and every effort will be made to restore VOR capability at the Whitehorse Airport as quickly as possible.

For further information, please contact:

Brian Stockall  
Manager, Level of Service and Aeronautical Studies – West  
NAV CANADA  
Edmonton ACC  
PO BOX 9867  
Edmonton International Airport  
Edmonton, AB T5J 2T2

Phone: (780) 890-3024  
Fax: (780) 890-4341  
Email: [stockab@navcanada.ca](mailto:stockab@navcanada.ca)