

RCO REDESIGN

Because the frequency selectors on some 25 kHz transceivers do not display the third decimal place, misunderstanding may exist in the selection of frequencies. With such transceivers, if the last digit displayed includes 2 and 7, then the equipment is capable of 25 kHz operations.

Example:

Muskoka RCO: 123.475 (actual frequency)

Aircraft Radio Display: 123.475 or 123.47

In either case, the aircraft radio is actually tuned to the proper frequency.
(TC AIM - COM 5.3)

**SELECT APPROPRIATE FIC FOR
AREA RCO MAP**

