



**Billy Bishop Toronto City Airport (CYTZ)
Notification of ILS Replacement – 2016**

NAV CANADA wishes to inform its customers that the Instrument Landing System (ILS) for runway 08 at the Billy Bishop Toronto City Airport will be replaced in the summer of 2016 as part of the National ILS Replacement Program. The installation of a new PARK AIR ILS system on runway 08 at Billy Bishop Toronto City Airport will address life cycle (reliability and integrity of service) and operational efficiency issues.

The planned outage period for runway 08 is from **18 July – 09 September, 2016**. Dates are subject to change depending upon weather conditions and contractor availability. Actual dates of scheduled outage will be published via NOTAM. Pilots should carefully monitor the NOTAM before and during the construction period for specific dates of the outage or other related disruptions.

NAV CANADA regrets any inconvenience to its customers; however, the importance of this navigation aid is recognised and every effort will be made to restore ILS operations on runway 08 at the Billy Bishop Toronto City Airport as quickly as possible.

For further information, please contact:

Gary Chandler
Manager, Program Coordination
NAV CANADA
77 Metcalfe Street
Ottawa, ON
K1P 5L6

Phone: (613) 563-3847
Fax: (613) 563-5602
Email: chandlg@navcanada.ca