


AIP CANADA (ICAO) SUPPLEMENT 43/17

ADJUSTMENTS TO SOUTHERN BOUNDARY OF CYA188 (A)(T) GLEN VALLEY, BRITISH COLUMBIA

NAV CANADA, the country's provider of civil air navigation services, has completed a cyclical review of the instrument procedures (IPs) for Abbotsford, British Columbia (BC) aerodrome CYXX.

As a result of this review and the application of new IP design criteria, the southern boundary of CYA188(A)(T) Glen Valley, BC must be adjusted 0.4 nautical miles (NM) north (see map sketch below). This adjustment is required so that the Abbotsford airport runway 07 instrument landing system (ILS) and non-directional beacon (NDB) instrument approach procedures will be compliant with the new criteria.

This change takes effect 12 October 2017 at 0901 Coordinated Universal Time (UTC). Refer to this AIP Supplement until the amended Vancouver visual flight rules (VFR) terminal area chart (VTA) (AIR 1901) is available in July 2018.



NOT SUITABLE FOR NAVIGATION

For further information please contact:

NAV CANADA
Customer Service Centre
77 Metcalfe Street
Ottawa, ON K1P 5L6

Tel.: 800-876-4693
Fax: 877-663-6656
E-mail: service@navcanada.ca

A handwritten signature in black ink, appearing to read 'James Ferrier', with a long horizontal flourish extending to the right.

James Ferrier
Director, Aeronautical Information Management