



NOTICE OF CHANGE

Medicine Hat, Alberta Decommissioning of the Medicine Hat 'YXH' VOR/DME

NAV CANADA, the country's provider of civil air navigation services, conducted an aeronautical study that reviewed the requirement for the Medicine Hat VOR/DME. The study concluded that the VOR/DME is not required and recommends that it be decommissioned. With this decommissioning the following changes will occur:

- The Medicine Hat airport VOR RWY 03 (GNSS) instrument approach procedure will be revoked;
- The segment of low level airway V300 from the Swift Current to Medicine Hat to Lethbridge VORs will be revoked and replaced with a low level fixed RNAV T-route; and
- The segment of high level airway J477 from Medicine Hat to the Canada/USA border will be revoked and high level fixed RNAV routes Q909 and Q832 will be extended from DESNU and VESDO respectively to a waypoint at that same location on the Canada/USA border.

These changes will take effect 15 October 2015 at 0901 Coordinated Universal Time (UTC).
The appropriate aeronautical publications will be amended.

For further information please contact:

Customer Service
NAV CANADA
77 Metcalfe Street
Ottawa, ON
K1P 5L6

Phone: 1-800-876-4693
Fax: 1-877-663-6656
Email: service@navcanada.ca